MIDMARK®

Installation Instructions

9A21300X CASTER BASE

KIT COMPONENTS

Part Number	Description	Qty.
9A21300X	Caster Base	1
046-0001-00	Allen Wrench (3/16”)	1
040-0312-13	5/16”-18 x 3/4” Flat Head Socket Screw	8
003-0743-00	Installation Instructions	1

REQUIRED TOOLS

3/16" Allen Wrench (Included)
4” x 4”-24” (10 cm x 10 cm-61 cm) wood support.

INTRODUCTION

Provides mobility to exam table.

WARNING

Assure all casters are locked to prevent movement during procedure. Do not use simultaneously with 9A14400X or 9A20800X Knee Crutch Assemblies.

INSTALLATION (1)



A. Raise FOOT all the way up.

DANGER

Unplug table from electrical outlet. Use precautions when lifting table. Failure to comply could cause personal injury or death.

B. Raise foot end of base and place a support beneath it.

C. Remove leveling screws.

INSTALLATION (2)



NOTE

Casters must be angled outward on base to prevent interference during procedures.

A. Place caster assembly in position and secure with two screws.

WARNING

After casters are installed on FOOT end, lock brakes on casters before proceding to install casters on HEAD end to prevent table movement.

B. After removing support from foot end and placing beneath head end, use same procedures to install casters.

OPERATION



WARNING

Assure brakes are in locked position before beginning a procedure.

A. Depress pedal to lock caster brake.

B. Raise pedal to unlock caster brake.

© Midmark Corporation - 1998

Print on Plain White Paper (Part No. 122919)

© Midmark Corporation - 1998